

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS
AK
2-ANCH,
4-

Animal Control Center
4711 S. Bragaw
Anchorage
Greater Anchorage Area Borough
Alaska

HABS No. AK-160

Note: These photographs were taken by Jet Lowe in summer 1991 for the book Buildings of Alaska, sponsored by the Society of Architectural Historians, who then donated the photographs to HABS. For more information on this site, see Alison K. Hoagland, Buildings of Alaska (New York: Oxford University Press, 1993), 98.

AK-160-1 NORTH FRONT

AK-160-2 INTERIOR, LOOKING NORTH